



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A. San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 6/14/17

Del Mar Union School District
Carmel Del Mar Elementary

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1174614	06/02/17	06:57 AM	SAMPLE 1	3710020-CBH-A	< 5	ug/L
W1174615	06/02/17	06:59 AM	SAMPLE 2	3710020-CBH-B	< 5	ug/L
W1174616	06/02/17	07:01 AM	SAMPLE 3	3710020-CBH-C	< 5	ug/L
W1174617	06/02/17	07:03 AM	SAMPLE 4	3710020-CBH-D	< 5	ug/L
W1174618	06/02/17	07:05 AM	SAMPLE 5	3710020-CBH-E	< 5	ug/L

Source **Source Description**

- SAMPLE 1 Childcare 1-2, West side of school, bubbler at sink
- SAMPLE 2 East side of 300 wing between girls / boys upper grade RRs, two single bubbler fountains, upper right fountain
- SAMPLE 3 300 wing, Classroom 303, bubbler at sink
- SAMPLE 4 east end of wing 100 between girls / boys lower grade RRs, two single bubbler fountains, lower left fountain
- SAMPLE 5 500 wing (Kindergarten), Classroom 501, bubbler at sink

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Doug Campbell, Senior Chemist