



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A. San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 6/27/17

Del Mar Union School District
Del Mar Hills Academy

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1174624	06/01/17	06:16 AM	SAMPLE 1	3710020-CBJ-A	< 5	ug/L
W1174625	06/01/17	06:18 AM	SAMPLE 2	3710020-CBJ-B	< 5	ug/L
W1174626	06/01/17	06:21 AM	SAMPLE 3	3710020-CBJ-C	< 5	ug/L
W1174627	06/01/17	06:27 AM	SAMPLE 4	3710020-CBJ-D	< 5	ug/L
W1174628	06/01/17	06:23 AM	SAMPLE 5	3710020-CBJ-E	< 5	ug/L

<u>Source</u>	<u>Source Description</u>
SAMPLE 1	Kindergarten Area, Exterior drinking fountain outside room 22, two single bubbler fountains, upper right fountain
SAMPLE 2	Room P-6, Childcare room, bubbler at sink
SAMPLE 3	Main bldg, Back of school in between Boys / Girls lower grade RRs, two single bubbler fountains, lower left fountain
SAMPLE 4	Main bldg, East of school in between Boys / Girls upper grade RRs, two single bubbler fountains, upper right fountain
SAMPLE 5	Main bldg, Room 18, bubbler at sink

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Tom Burger, Associate Chemist