



Environmental Monitoring and Technical Services  
2392 Kincaid Road MS 45A, San Diego, CA 92101  
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services  
Lead School Testing  
Report Date: 6/14/17

Del Mar Union School District  
**Sage Canyon**

| Sample ID | Sample Date | Sample Time | Source   | External ID   | Lead | Units |
|-----------|-------------|-------------|----------|---------------|------|-------|
| W1175404  | 06/06/17    | 06:06 AM    | SAMPLE 1 | 3710020-CCB-A | < 5  | ug/L  |
| W1175405  | 06/06/17    | 06:09 AM    | SAMPLE 2 | 3710020-CCB-B | < 5  | ug/L  |
| W1175406  | 06/06/17    | 06:13 AM    | SAMPLE 3 | 3710020-CCB-C | < 5  | ug/L  |
| W1175407  | 06/06/17    | 06:16 AM    | SAMPLE 4 | 3710020-CCB-D | < 5  | ug/L  |
| W1175408  | 06/06/17    | 06:18 AM    | SAMPLE 5 | 3710020-CCB-E | < 5  | ug/L  |

Source      Source Description

- SAMPLE 1      Childcare, Sink in childcare room A / B, bubbler at sink
- SAMPLE 2      200 wing, classroom 201 (kindergarten), bubbler at sink
- SAMPLE 3      400 wing, Sink in hallway across from classroom 405, bubbler at sink
- SAMPLE 4      north end of 300 wing, two single bubbler fountains on pedestal, lower left bubbler when facing wall
- SAMPLE 5      MUR, Drinking fountain behind MUR by boys restroom, two single bubbler fountains, upper right fountain

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L  
Action Level (AL) = 15 ug/L

  
Doug Campbell, Senior Chemist