



Environmental Monitoring and Technical Services  
2392 Kincaid Road MS 45A, San Diego, CA 92101  
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services  
Lead School Testing  
Report Date: 6/14/17

Del Mar Union School District  
**Sycamore Ridge**

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1175389	06/02/17	06:12 AM	SAMPLE 1	3710020-CCC-A	< 5	ug/L
W1175390	06/02/17	06:14 AM	SAMPLE 2	3710020-CCC-B	< 5	ug/L
W1175391	06/02/17	06:16 AM	SAMPLE 3	3710020-CCC-C	< 5	ug/L
W1175392	06/02/17	06:18 AM	SAMPLE 4	3710020-CCC-D	< 5	ug/L
W1175393	06/02/17	06:22 AM	SAMPLE 5	3710020-CCC-E	< 5	ug/L

**Source**      **Source Description**

- SAMPLE 1    ASP building, in between ASP 1- ASP 2, two single bubbler fountains, upper right fountain
- SAMPLE 2    Classroom ASP 1, bubbler at sink
- SAMPLE 3    Eastside of F wing, exterior, two single bubbler fountains, lower left fountain
- SAMPLE 4    South side of E-wing in between boys and girls RRs, two single bubbler fountains, upper right fountain
- SAMPLE 5    Westside of building B left side of custodian room, two single bubbler fountains, lower left fountain

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L  
Action Level (AL) = 15 ug/L

  
Doug Campbell, Senior Chemist