



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A. San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 6/14/17

Del Mar Union School District
Torrey Hills

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1175394	06/06/17	07:08 AM	SAMPLE 1	3710020-CCD-A	< 5	ug/L
W1175395	06/06/17	06:58 AM	SAMPLE 2	3710020-CCD-B	< 5	ug/L
W1175396	06/06/17	06:55 AM	SAMPLE 3	3710020-CCD-C	< 5	ug/L
W1175397	06/06/17	07:02 AM	SAMPLE 4	3710020-CCD-D	< 5	ug/L
W1175398	06/06/17	07:06 AM	SAMPLE 5	3710020-CCD-E	< 5	ug/L

Source **Source Description**

- SAMPLE 1 Boys / girls upper grade restrooms (next to custodial room), two single bubbler fountains, upper right fountain
- SAMPLE 2 Boys / girls lower grade restrooms (next to custodial room), two single bubbler fountains, lower left fountain
- SAMPLE 3 K building, Classroom K-5, bubbler at sink
- SAMPLE 4 Classroom H-1, bubbler at sink
- SAMPLE 5 Classroom C-1, bubbler at sink

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Doug Campbell, Senior Chemist